TENTION - MUST SHIP FROAU

Dart Aerospace Ltd.

Tuesday, 03/10/2006 8:40:31 Af

Linda Lacelle User

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**  : 28813

P.O. Number

: 10606 : NIA

This Issue

: 03/10/2006

S.O. No. : NA

Prsht Rev. First Issue : NC : MA

Type : SMALL /MED FAB

: 28808 **Previous Run** Written By

Checked & Approved By : Est:

Comment

05.05.12 New issue KJ/JLM Est Rev:B Now on Waterjet 06-10-03 JLM **Drawing Name** 

: WEARPLATE

**Part Number** 

**Drawing Number** 

: D33193 . D3319 REV. B

**Project Number Drawing Revision** 

: N/A

Material **Due Date** 

: 06/10/2006

Qty:

6 Um:

Each

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

M1010S18GA

1010/1025/A21/6aA SHEET .048



Comment: Qty.:

3.4150 sf(s)/Unit Total: 20.4901 sf(s)

1010/1025/A21/6aA SHEET .048" Thick

Batch: 100000

06 10 04

2.0

WATER JET



**Comment: FLOW WATER JET** 

1-Cut as per Dwg D3319

Prog Rev:\_P

M & 10 04

2-Deburr if necessary

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE





Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0 QC8

SECOND CHECK

Comment: SECOND CHECK

5.0



SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr if necessary

# **Dart Aerospace Ltd**

DuitAu	OSPACE	Ltu								
W/O:			WC	RK ORDER CHAI	NGES		<u> </u>	<del></del>		
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Oate Qty Approval Chief Eng / Prod Mgr		Approval QC Inspector
				·				•		
			_							
Part No	:	PAR #:	Fault Cate	jory:	NCI	R: Yes I	No DQA	\:	_ Date: _	
						QA: N/	C Closed	: <u> </u>	_ Date: _	
NCR:			WORK ORDE	R NON-CONFOR	MANCE	(NCR	).		. •	
DATE	STEP	Description of NC	<u> </u>		Section B		Verific	ation	tion Approval Ap	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	on .	Sign & Date	Sectio	n C		QC Inspector
		•					***	*177		
			-							
					!		·.			-
										,

NOTE: Date & initial all entries

	a Lacelle	Process Sheet	
Customer:	CU-DAR001 Dart Helicopters Ser	vices Drawing Name: WEAR	RPLATE
Job Number:	28813	Part Number: D3319	93
Job Number:			
Seq. #:	Machine Or Operation:	Descriptio	on:
6.0	BRAKE NC	NC BRAKE	
Comme	ent: NC BRAKE	A	Sa allida
7.0	Form using DT8326 & DT82	61 as per Dwg D3319 Rev: DIMENSHONAL CHECK	
		( 10.05 C)	
	ent: DIMENSIONAL CHECK	LARGE FABRICATION RESOURCE 1	
8.0	LARGE FAB 1	LANGE PABRICATION RESOURCE T	
Comme	ent: LARGE FABRICATION RES		
	Qty Part Number Des	319-3T2 per QSI 004 and Dwg D3319 Rev: ① cription Batch Hardcoat Rod M 101247	Col. 06-10-05 6
9.0	QC9	VISUAL WELDING INSPECTION	Cyc 0 (6-10 t.)
	ent: VISUAL WELDING INSPEC		PD 0610-06 (6)
10.0	POWDER COATING	POWDER COATING	
Comme	ent: POWDER COATING	(D. (. 4.0.5.0) OCI 005.4.2	
11.0	Powder Coat Grey Sandtex QC3	(Ref: 4.3.5.6) as per QSI 005 4.3  INSPECT POWDER COAT/CHEMICAL	06-10-06 (b)
			FC - 06 10 06 (6)
12.0	PACKAGING 1	PACKAGING RESOURCE #1	PC 00 10 00 (6)
12.0	PACING I	THORIGINO NECOCIOE #1	
Comme	ent: PACKAGING RESOURCE # Identify on inside surface us TCCA-PDA, Dart Aerospace P/N: D3319-3, B/N: BXXXXX For Product Eligibility see Pl and Stock	ing a permanent fine point marker with the follow Ltd. 〈	
	Location:	5+361 Y	B 06/10/06 (6)
	·		

## **Dart Aerospace Ltd**

	. oopaoi								
W/O:	·		WO	RK ORDER CHANG	GES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			<u>,                                    </u>						
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	NO DQ	<b>A</b> : 🗀	_ Date:	6116186
					QA: I	N/C Close	d:	Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCI	₹)			
DATE	STEP	Description of NC			ction B	Verific	ation	Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 6 Date	Secti	on C	Chief Eng	QC Inspector
^ i									
									-

NOTE: Date & initial all entries

Date: User: Tuesday, 03/10/2006 8:40:31 AM

Linda Lacelle

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPLATE

Job Number: 28813

Part Number: D33193

Job Number:



Seq. #:

Job Completion

**Machine Or Operation:** 

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE




U 06-10°06


### **Dart Aerospace Ltd**


Duitho	·oopao	J Ltu								
W/O:			WO	RK ORDER CHANG	GES			***	•	
DATE	STEP	PRO	CEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-							
* #										
Part No	•	PAR #:	Fault Cateo	lorv.	NCD.	Vac N	lo DO		Data	
1 411 140	•	I All #.	raun categ	Oly					_ Date: _ _ Date: _	
NCR:		V	VORK ORDE	R NON-CONFORM	IANCE (	(NCR)				
DATE	STEP	Description of NC			ction B	0:	Verific		Approval	Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
								;		


NOTE: Date & initial all entries











### D3319-5 WEARPLATE

붘S

DOCUMENT

Ø

Copyright © 2004 by DART AEROSPACE LTD PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE

500


ANY

PURPOSE

ဝ္က

COPIED

- 1) MATERIAL: AISI 1010-1025 OR ASTM A36/A366/A1008 OR CSA G40-21, 38W/44W/50W/60W/70W SERIES STEEL 18 GAUGE (0.048 THICK)
- 2) FINISH: POWDER COAT GREY SANDTEX (REF.4.3.5.6) PER DART QSI 005 4.3
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) PART IS SYMMETRICAL ABOUT CENTERLINE
- 5) ALL DIMENSIONS IN INCHES
- 6) WELD PER DART QSI 004
- 7) IDENTIFY ON INSIDE SURFACE AS INDICATED USING FINE POINT PERMANENT INK MARKER: "TCCA-PDA, DART AEROSPACE LTD., P/N D3319-5 B/N BXXXXX, FOR PRODUCT ELIGIBILITY SEE PDA05-18"



### D3319-7 WEARPLATE


- 1) MATERIAL: AISI 1010-1025 OR ASTM A36/A366/A1008 OR CSA G40-21, 38W/44W/50W/60W/70W SERIES STEEL 18 GAUGE (0.048 THICK)
- 2) FINISH: POWDER COAT GREY SANDTEX (REF.4.3.5.6) PER DART QSI 005 4.3
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) PART IS SYMMETRICAL ABOUT CENTERLINE
- 5) ALL DIMENSIONS IN INCHES
- 6) WELD PER DART QSI 004
- 7) IDENTIFY ON INSIDE SURFACE AS INDICATED USING FINE POINT PERMANENT INK MARKER: "TCCA-PDA, DART AEROSPACE LTD., P/N D3319-7 B/N BXXXXX, FOR PRODUCT ELIGIBILITY SEE PDA05-18"



WEARDI ATE		05 05 05
TITLE		DATE
D3319 SHEET 4 OF 5	全	¥
DRAWING NO. REV. B	APPROVED,	CHECKED /
HAWKESBURY, ONTARIO, CANADA	全	至
DART AFROSPACE ITD	DRAWN BY	DESIGN



DESIGN PH	DRAWN BY		OSPACE LTD ONTARIO, CANADA
CHECKED	APPROVED , at	DRAWING NO.	REV. B
4	c#	D3319	SHEET 5 OF 5
DATE		TITLE	SCALE
05.06.06		WEARPLATE	1:3



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

C) Aiv

DART AEROSPACE LTD	Work Order:	28813
Description: Wear plate	Part Number:	03319-3
· ·		2
nspection Dwg: 73319 Rev: R		Page 1 of 1

	FIRST	ARTICLE IN	SPECTI	ON CHE	CKLIST	C ~ ~ ~
	X	First Artic	ile 💙	Prote	otype	Elt
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
75.52	+1-0.030	75.50	<i>3</i> √		Mensucing -	NADE
4.518	41-0.010	4.545	J		Nech '	
X3.16x.607	+1-0.010	1.316x.607	<b>V</b>		verd	
316x.607	+1-0.010	.316x . 607	<b>√</b>		Vern	
316x.607	11-0.010	316x2607	$\checkmark$		verv	
0.190	+0.005-0.001	0.193	$\sqrt{}$		VerN	
6.163	+1-0.010	6.169	√ .		vern	
8690	+1-0.010	8.696	$\checkmark$		VerN	
0.500	+0.006-0.001	0.500	<b>√</b>	·	Yern	
5.063	11-0.010	5.068	<b>√</b>		vern	
2.940	41-0.010	2.946	1		Vern	
0.60	+1-0.030	0.60	V		VerN	•
3.527	+1-0.010	3.527	$\checkmark$		VerN	
2.690	71-0.010	2.695	<b>/</b>		verN	
			·			
			`			
						·.
			Ì			
	·					
Measured by:	M:M/ A	udited by:	1	Pro	ototype Appro	val:
Date: (	8 10 04		10.05		Da	ate:
Rev Date	Change					sed by Approve
	Name Indian				. , K.1/1	IM !

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	L